



- Surface-Mounted
- ADA compliant – opens with less than 5 lbs. of force, projects less than 4" from the wall when closed
- Model 964 – Gray **Bradex**[®]

Product Materials

Bacterial resistant high density polyethylene with steel to steel support hinges. Pneumatic gas shock mechanism opens and closes unit smoothly. ADA compliant nylon buckle is adjustable with one hand.

STRENGTH NOTE: Unit to be able to support a static load of up to 50 lbs.

Installation

Verify all rough-in dimensions prior to installation. Secure to wall through mounting holes. Mounting hardware for typical conditions is included.

⚠ WARNING The installer is responsible for confirming the wall construction, anchors and fasteners are in good condition and capable of withstanding 200 pounds pull out force or greater. Contact the building architect or engineer for confirmation when in doubt.

⚠ WARNING: Be sure to use reinforced backing behind wall where mounting screws or anchoring devices are installed to ensure adequate support for the toddler wall seat. All anchoring devices must be appropriate for specific wall construction. Severe personal injury and/or property damage may result from improper mounting.


Guide Specification

Surface-mounted toddler wall seat shall be gray colored (964) molded bacterial-resistant, high density polyethylene. Steel to steel support hinges with pneumatic gas shock mechanism. Unit shall have an anti-microbial safety belt. Warning labels are printed in English, Spanish, French and Braille. Unit shall be operable with less than 5 lbs. of force.

Overall dimensions:

Closed: 12"W x 15-1/5"H x 4"D

Open: 12"W x 15-1/2"H x 13-1/2"D



ADA Compliant

- Consult local and national accessibility codes for proper installation guidelines.
- Conformity and compliance to local and national codes is the responsibility of the installer.

Service Parts Available

Part Number	Description
P15-495	Replacement Strap

Orders composed of products indicated as **Bradex**[®] will be available to ship in three days after receipt of order at the factory. There is no pricing penalty for this service from Bradley.